Master
Slave
M_Idle
Slave_In_Idle
S_Idle
M_Busy
Cmd_Start
Timeout
Slave_In_Busy
S_Busy
M_Done
OK
S_Done